

VISA S.p.A. – GENERATING SETS and POWER SOLUTIONS HEADQUARTERS & HEAD OFFICE

via I Maggio, 55 · Fontanelle (TV) 31043 · ITALY tel: +39 0422 5091 · visa@visa.it · www.visa.it MILAN area - LOCAL OFFICE via Luigi Galvani, 12 · Zelo Buon Persico (LO) 26839 · ITALY tel: +38 324 638721



Fontanelle 26<sup>th</sup> October 2023

# **TECHNICAL RECALL CAMPAIGN**

Dear Customer,

We wish to inform you that Visa S.p.A., in its ongoing pursuit of enhancing the quality and safety standards of its machinery, has voluntarily undertaken a product update as detailed below.

**SUBJECT:** Excitation Wiring of Battery Charging Alternator

## **POTENTIAL MALFUNCTION:**

While it is important to note that no actual malfunctions have been reported at this time, during a testing campaign, we have identified that, in rare cases, the battery charging alternator may not operate at its full capacity due to a lack of excitation. This situation may occur in instances where the machine is used in a mobile capacity with a discharged battery and irregular usage patterns. In such cases, the engine may start, but the battery charging alternator may fail to excite and consequently not provide voltage output. This, in turn, leads to a complete battery discharge, rendering the machine unusable for subsequent start-ups.

### MACHINES INVOLVED:

Onis Visa generating sets with DOOSAN stage V engines (models D18/D24/D34), including the following genset models:

DS35 - DS45 - DS65





#### VISA S.p.A. - GENERATING SETS and POWER SOLUTIONS

HEADQUARTERS & HEAD OFFICE via I Maggio, 55 · Fontanelle (TV) 31043 · ITALY tel: +39 0422 5091 · visa@visa.it · www.visa.it

MILAN area - LOCAL OFFICE via Luigi Galvani, I2 · Zelo Buon Persico (LO) 26839 · ITALY tel: +39 334 6387211



INSTRUCTIONS FOR MODIFICATION		
	Safety Notes: Any work on the Generator Set should be carried out by qualified personnel. Before making modifications, please read the Generator Set manual and refer to the accompanying documents (electrical diagram, controller manual). It is necessary to turn off the generator set and disconnect the battery before proceeding.	
	Required tools:         -       Scissors         -       Flat-head screwdriver         -       Crimping pliers         -       Insulated connector         -       Insulated cap	
<ul> <li>Identify the X2 connector on the exterior of the electrical panel (highlighted in red in the photo below) and disconnect it to work without power.</li> <li>Consider the connector on the panel side (in the photo on the left)</li> </ul>		
2. Identify	the jumper between pin J and D	





#### VISA S.p.A. - GENERATING SETS and POWER SOLUTIONS

HEADQUARTERS & HEAD OFFICE via I Maggio, 55 · Fontanelle (TV) 31043 · ITALY tel: +39 0422 5091 · visa@visa.it · www.visa.it MILAN area - LOCAL OFFICE via Luigi Galvani, 12 · Zelo Buon Persico (LO) 26839 · ITALY tel: +39 334 6387211





<b>-</b>	VALMEC - METALWORKS DEPT. METALWORKS
<b>a</b> lmec	tel: +39 0422 5093 info@valmec.it

METEOR' - SOUNDPROOF DEPT. SOUNDPROOF MATERIALS and sound insuLation systems tel: +39 0422 509411 info@insonorizzantiit

 Cut the wire near pin D of connector X2, leaving about 1 cm of wire, and insulate the wire with an insulated cap.







Identify wire 17 connected to pin G of connector X2.
 Cut wire 17 approximately 10 cm away from the connector, and connect the two wire 17 terminals together with the previously cut wire connected to pin J









5. The final result should look like this.



6. Reconnect the connector





#### VISA S.p.A. - GENERATING SETS and POWER SOLUTIONS

**HEADQUARTERS & HEAD OFFICE** via I Maggio, 55 · Fontanelle (TV) 31043 · ITALY

tel: +39 0422 5091 · visa@visa.it · www.visa.it MILAN area - LOCAL OFFICE via Luigi Galvani, 12 · Zelo Buon Persico (LO) 26839 · ITALY

tel: +39 334 6387211



Nettunc

**NETTUNO<sup>®</sup> – WATER DEPT.** IRRIGATION SOLUTIONS AND MOTORPUMPS

tel: +39 0422 5092 info@nettuno-irrigazione.com

VALMEC - METALWORKS DEPT. METALWORKS \* tel: +39 0422 5093 valmec nfo@valmec.

**METEOR' - SOUNDPROOF DEPT.** SOUNDPROOF MATERIALS and SOUND INSULATION SYSTEMS

METEOR' tel: +39 0422 509411 info@insonorizzanti.it

### **ELECTRICAL DIAGRAM**





Mauro Zanuto VISA S.p.A.

